

Apple IIGS Incompatibilities: ProFile Interface Cards

Revised: 10/12/87 Security: Everyone

Apple IIGS Incompatibilities: ProFile Interface Cards

This article last reviewed: 22 September 1986

The Apple IIGS is designed to be used with the vast majority of Apple IIe hardware and software. However, there are some design differences that will cause some products to be incompatible with the Apple IIGS.

Some Apple ProFile Interface Cards work incorrectly in an Apple IIGS and cause the information on the ProFile to be inaccessible. To avoid problems when using a ProFile in an Apple IIGS, either modify the interface card or obtain the new version of the card.

The Apple IIGS bus' higher 'noise' levels create the problem. The 'noise' is passed on to the ground traces on the ProFile interface card and will eventually (after use) corrupt the directory of the ProFile, rendering it invisible to ProDos and inaccessible to the user.

Tech Info Library Article Number: 2050